

Entry level Activities & Schemes Undertaken with the 1st released Installment				
Sl.No	Name of the Scheme	Fund Utilized (Rs.in Lakh)	Completion Status	Observation
1	Entrance Gate/ Welcome Gate (RSL-29)	2.00	100%	Entry gate although completed, was not found to be satisfactory. Instructions given to install/construct a concrete sinage showing village map and strategic landmarks of the village.
2	Boundery Wall at Borpathar L.P School/ Borpathar M.E. School & Anganwadi Centre (RSL-30)	7.86	100%	Scheme is apparently over estimated.
3	Development of Borpathar Anganwadi Centre & Children Park (RSL-31)	1.44	100%	Sign Board was wrongly written, which was instructed to be rectified. Also, the swings installed in front of the AWC was found to have no seats, wherein the kids can play. Instructions were given to fix the seats immediately.
4	Waiting shed at Borpathar Bus Stoppage (RSL-32)	1.00	100%	Although found to be completed, the shed appeared abandoned and not used by public.
5	Paver Block at Borpathar Bus Stoppage (RSL-33)	2.30	100%	Scheme is apparently over estimated and also as informed the stoppage has not been used till date.
6	Development of Parijat Yubok Sangha at Borpathar	1.50	100%	Scheme is found to be completed as per plan & estimate
7	Latrin cum Urinal at Parijat Yubok Sangha (RSL-35)	1.00	100%	Construction is found to be completed
8	Installation of Mark 3 Tubel at Parijat Yubok Sangha (RSL-36)	0.88	100%	Installation is found to be completed
9	Development of Ujani Borpathar Namghar (RSL-37)	2.80	100%	Construction is found to be completed. However, the scheme is apparently over estimated in comparision to the works executed.
10	Development of Middle Borpathar Namghar (RSL-38)	1.70	100%	Construction is found to be completed. However, the scheme is apparently over estimated in comparision to the works executed.
11	Construction of Dustbin 5 nos at Borpathar (RSL-39)	1.78	100%	Construction of all the 5 dustbins were seen to be completed. However, the locations of the dustbins were not found to be proper and hence its utility was not seen. None of the dustbins were located in prime locations of the village like market areas etc.